	Ge	neral	
SPCC Type:	Tanker-truck loading rack	SPCC Custodian:	
Capacity:	N/A	Phone No.:	
Fuel Type:	JP-5	Facility:	
Year Installed:	02	Building:	1963
Type of Service:	Bulk mobile tank filling	Map & Grid No.:	6B, H-17
Condition:	Good	Corrosion Protection:	N/A
Color:	N/A	Support:	N/A
Fuel Markings:	N/A	Shape:	N/A
Surrounding Surface:	Concrete	Material:	Concrete
	Secondary	Containment	V-11 -4
Type:	Volved storm-water system	Hacility I brainage:	
Type: Condition:	Valved storm-water system N/A	Facility Drainage: Outfall:	Valved storm-water system St. John's River
Condition:	Valved storm-water system N/A N/A	Outfall:	St. John's River
Condition: Lining:	N/A	•	•
	N/A N/A	Outfall:	St. John's River
Condition: Lining: Dim. (LxWxH):	N/A N/A Security	Outfall: Valve Locking: / Lighting	St. John's River Locked
Condition: Lining:	N/A N/A Security Adequate	Outfall: Valve Locking:	St. John's River Locked
Condition: Lining: Dim. (LxWxH): Lighting Adequacy:	N/A N/A Security Adequate Adequate	Outfall: Valve Locking: / Lighting	St. John's River

FOR COMPLIANCE:

40 CFR 112: 1) Ensure that the primary valves to storm-water system are locked shut at all times and that the system could handle the volume of the largest tank filled at the loading racks.

BEST MANAGEMENT PRACTICE:

1) Erect curbing around the entire parking/load rack area at facility 1963. The current configuration could not handle a worst-case scenario.